



TRENT
PRODUCTS

Tel: 01782 - 844688 Fax: 01782 - 844772

PM-1icx & PM-2icx FAN POWER MONITOR
3 PHASEWIRING & CONNECTION DIAGRAM

DATE:

05/01/06

DRAWING No:

PM-icx - 3P-WD01

DRAWN BY

MAE

NOTES:

- 1) LOCAL ISOLATION MUST BE PROVIDED IN ACCORDANCE WITH THE CURRENT EDITION OF THE IEE REGULATIONS.
- 2) CHECK MANUFACTURER'S WIRING DETAILS FOR CORRECT CONNECTIONS AND SET-UP REQUIREMENTS.
- 3) ENSURE THAT THE POWER SUPPLY IS CORRECTLY FUSED TO THE SIZE OF THE FAN MOTOR AND THAT OVERLOAD PROTECTION IS FITTED TO THE CURRENT REGULATIONS.
- 4) ENSURE THAT THE POWER SUPPLY IS CORRECT FOR THE LOADING OF THE POWER MONITOR AND / OR GAS VALVE.

IF IN DOUBT, ASK