



- NOTES:**
- 1) LOCAL ISOLATION MUST BE PROVIDED IN ACCORDANCE WITH THE CURRENT EDITION OF THE IEE REGULATIONS.
 - 2) CHECK MANUFACTURER'S WIRING DETAILS FOR CORRECT CONNECTIONS AND SET-UP REQUIREMENTS.
 - 3) ENSURE THAT THE SWITCHED POWER IS CORRECTLY FUSED TO THE LOADING OF THE CATERSENSE AND PLANT ITEMS.

| | | | | |
|---|--|-----------------|------------------------------------|-----------------|
| <p>TRENT PRODUCTS</p> <p>Tel: 01782 - 844688 Fax: 01782 - 844772</p> | <p><i>IF IN DOUBT, ASK</i></p> | <p>DATE:</p> | <p>DRAWING No:</p> | <p>DRAWN BY</p> |
| | <p>CATERSENSE -3 (03-01) WIRING & CONNECTION DIAGRAM</p> | <p>05/01/06</p> | <p>CATERSENSE - 3 WD-03-01</p> | <p>MAE</p> |