



- NOTES:**
- 1) LOCAL ISOLATION MUST BE PROVIDED IN ACCORDANCE WITH THE CURRENT EDITION OF THE IEE REGULATIONS.
 - 2) CHECK MANUFACTURER'S WIRING DETAILS FOR CORRECT CONNECTIONS AND SET-UP REQUIREMENTS.
 - 3) ENSURE THAT THE SWITCHED POWER IS CORRECTLY FUSED TO THE LOADING OF THE CATERSENSE AND PLANT ITEMS.

TRENT PRODUCTS <small>Tel: 01782 - 844688 Fax: 01782 - 844772</small>	<i>IF IN DOUBT, ASK</i>	DATE:	DRAWING No:	DRAWN BY
	CATERSENSE -3 (03-04) WIRING & CONNECTION DIAGRAM	05/01/06	CATERSENSE - 3 WD-03-04	MAE